



# PIC18F1220/1320

## PIC18F1220/1320 Rev. B1 Silicon/Data Sheet Errata

The PIC18F1220/1320 Rev. B1 parts you have received conform functionally to the Device Data Sheet (DS39605C), except for the anomalies described below.

All of the issues listed here will be addressed in future revisions of the PIC18F1220/1320 silicon.

The following silicon errata apply only to PIC18F1220/1320 devices with these Device/Revision IDs:

Part Number	Device ID	Revision ID
PIC18F1220	00 0111 111	00010
PIC18F1320	00 0111 110	00010

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFh in the device's configuration space. They are shown in hexadecimal in the format "DEVID2 DEVID1".

### 1. Module: Core

Certain combinations of code sequence, code placement, VDD, FOSC and temperature may cause the corruption of fetched instructions. A corrupted instruction fetch will cause the part to execute an incorrect instruction with unpredictable results.

Microchip cannot predict which combinations of these conditions will cause this failure.

If this failure mechanism exists in your system, it should become evident during statistically significant preproduction testing using your particular code sequence and placement (the minimum suggested sample size is 100 units). Preproduction testing should exercise all the functions of your application across system variables. Any changes to code should be tested in the same manner prior to being implemented.

This issue has not been observed for FOSC up to 4 MHz with VDD up to 5.25V. If failures occur while meeting both of these conditions, then the failures are likely not related to this failure mechanism.

#### Work around

Use the part at or below 4 MHz with VDD at or below 5.25V.

Change the placement of code within program memory.

Use the next revision of silicon when it becomes available.

#### Date Codes that pertain to this issue:

All engineering and production devices.

### 2. Module: Data EEPROM

When reading the data EEPROM, the contents of the EEDATA register may be corrupted if the RD bit (EECON1<0>) is set immediately following a write to the address byte (EEADR). The actual contents of the data EEPROM remain unaffected.

#### Work around

Do not set EEADR immediately before the execution of a read. Write to EEADR at least one instruction cycle before setting the RD bit. The instruction between the write to EEADR and the read can be any valid instruction, including a NOP.

#### Date Codes that pertain to this issue:

All engineering and production devices.

### 3. Module: Core (DAW Instruction)

The DAW instruction may improperly clear the Carry bit (STATUS<0>) when executed.

#### Work around

Test the Carry bit state before executing the DAW instruction. If the Carry bit is set, increment the next higher byte to be added, using an instruction such as INCFSZ (this instruction does not affect any Status flags and will not overflow a BCD nibble). After the DAW instruction has been executed, process the Carry bit normally (see Example 1).

#### EXAMPLE 1: PROCESSING THE CARRY BIT DURING BCD ADDITIONS

```
MOVLW 0x80      ; .80 (BCD)
ADDLW 0x80      ; .80 (BCD)

BTFSC STATUS, C ; test C
INCFSZ byte2    ; inc next higher LSB
DAW
BTFSC STATUS, C ; test C
INCFSZ byte2    ; inc next higher LSB

This is repeated for each DAW instruction.
```

#### Date Codes that pertain to this issue:

All engineering and production devices.

# PIC18F1220/1320

---

## 4. Module: INTOSC

Incrementing or decrementing the value in the OSCTUNE register may not have the expected effect of shifting the INTRC or INTOSC output frequencies. The OSCTUNE values for which this happens may vary with temperatures above 70°C.

### **Work around**

None

### **Date Codes that pertain to this issue:**

All engineering and production devices.

## 5. Module: Internal Oscillator Block

At high temperature (above 85°C) or low V<sub>DD</sub> (below 2.5V), the IOFS bit (OSCCON<2>) may not become set when the internal oscillator block is selected as the system clock source for any frequency above 31 kHz (OSCCON<6:4> ≠ 000). The INTOSC output will stabilize at 8 MHz; however, the IOFS bit may not become set.

### **Work around**

If time critical code is to be executed, it should be delayed by 1 ms following the operation that enables the 8 MHz INTOSC output from the internal oscillator block.

### **Date Codes that pertain to this issue:**

All engineering and production devices.

## 6. Module: Internal Oscillator Block

If the INTRC clock source was not started at POR (any V<sub>DD</sub>) and V<sub>DD</sub> is greater than 4.5V, the INTRC clock source may not start or may require a long delay when starting. The INTRC may not restart when V<sub>DD</sub> is lowered below 4.5V.

Features that depend on the operation of the INTRC clock source may be affected. These include the INTOSC output when exiting from Sleep mode, the Watchdog Timer (WDT) if enabled by firmware using the WDTCON register, Two-Speed Start-ups during Reset or wake-up from Sleep and the Fail-Safe Clock Monitor (FSCM) when exiting Sleep mode.

The INTOSC frequency may rise very high (for example, 9.5 MHz). The WDT and the FSCM may simply not function. Two-Speed Start-ups may not occur but execution will start once the primary clock source becomes ready.

### **Work around**

Several work arounds may be used.

1. Enable the WDT in Configuration register, CONFIG2H, and place a CLRWDT instruction somewhere in the main loop.
2. Configure the internal oscillator block as the primary clock source using Configuration Register 1H.
3. Any technique that starts the INTRC at Reset and does not disable it may be used.
4. Ensure that V<sub>DD</sub> is below 4.5V when starting the INTRC clock source.

There may be other work arounds.

### **Date Codes that pertain to this issue:**

All engineering and production devices.

## 7. Module: EUSART

The CREN bit may be cleared when the EUSART completes an auto-baud measurement.

### Work around

When the auto-baud measurement is complete, the CREN bit must be set by firmware.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 8. Module: EUSART

If the TXEN bit is set when an auto-baud measurement is completed, the EUSART may transmit an arbitrary byte.

### Work around

Clear the TXEN bit before performing the auto-baud measurement. When the measurement is complete, set the TXEN bit.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 9. Module: EUSART

The auto-baud measurement may not determine the correct baud rate if the ABDEN bit is set while the RB4/RX pin is low.

### Work around

If the wake-up function is being used (WUE is set), wait for the RB4/RX pin to go high following a Break signal before setting the ABDEN bit.

If the wake-up function is not being used, ensure that RB4/RX is Idle (high between bytes) before setting the ABDEN bit.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 10. Module: Data EEPROM

When writing to the data EEPROM, the contents of the data EEPROM memory may not be written as expected.

### Work around

Either of two work arounds can be used:

1. Before beginning any writes to the data EEPROM, enable the LVD (any voltage) and wait for the internal voltage reference to become stable. LVD interrupt requests may be ignored. Once the LVD voltage reference is stable, perform all EEPROM writes normally. When writes have been completed, the LVD may be disabled.
2. Configure the BOR as enabled (any voltage). Select a threshold below VDD to allow normal operation. If VDD is below the BOR threshold, the device will be held in Brown-out Reset.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 11. Module: Reset

It has been observed that in certain Reset conditions, including power-up, the first GOTO instruction at address 0x0000 may not be executed. This occurrence is rare and affects very few applications.

To determine if your system is affected, test a statistically significant number of applications across the operating temperature, voltage and frequency ranges of the application. Affected systems will repeatably fail normal testing. Systems not affected will continue to not be affected over time.

### Work around

Insert a NOP instruction at address 0x0000.

### Date Codes that pertain to this issue:

All engineering and production devices.

# PIC18F1220/1320

## Clarifications/Corrections to the Data Sheet

In the Device Data Sheet (DS39605C), the following clarifications and corrections should be noted.

### 1. Module: CCP

In **Section 14.0 “Timer3 Module”**, bit 6 of the T3CON register was incorrectly defined as “unimplemented”. The correct definition for T3CON<6> is T3CCP2 and is shown in **bold** below:

#### REGISTER 14-1: T3CON: TIMER3 CONTROL REGISTER

R/W-0	<b>R/W-0</b>	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
RD16	<b>T3CCP2</b>	T3CKPS1	T3CKPS0	T3CCP1	$\overline{\text{T3SYNC}}$	TMR3CS	TMR3ON
bit 7						bit 0	

bit 6, 3     **T3CCP2:T3CCP1**: Timer3 and Timer1 to CCP Enable bits  
 1x = Timer3 is the clock source for compare/capture CCP module  
 01 = **Reserved**  
 00 = Timer1 is the clock source for compare/capture CCP module

### 2. Module: Data EEPROM Memory

In Table 22-1 on page 254 of the Device Data Sheet, the typical value for parameter D122, Data EEPROM Erase/Write Cycle Time (TDEW) has changed. The new value is 5.5 ms and is shown in **bold** below.

**TABLE 22-1: MEMORY PROGRAMMING REQUIREMENTS**

DC CHARACTERISTICS			Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for industrial				
Param No.	Sym	Characteristic	Min	Typ†	Max	Units	Conditions
D122	TDEW	Erase/Write Cycle Time	—	<b>5.5</b>	—	ms	

## REVISION HISTORY

### Rev A Document (06/2003)

First revision of this document, silicon issues 1 (Data EEPROM), 2 (Data EEPROM), 3 (Core), 4 (INTOSC), 5 (Internal Oscillator Block), 6 (Internal Oscillator Block), 7 (Electrical Specifications), 8 (EAUSART), 9 (EAUSART) and 10 (EAUSART) and Data Sheet Clarification issues 1 (Internal RC Accuracy) and 2 (DC Characteristics Table).

### Rev B Document (10/2003)

Added silicon issue 1 (Core).

### Rev C Document (12/2003)

Removed silicon issue 2 (Data EEPROM). Changed silicon issue 8, 9 and 10 (was issue 9, 10 and 11) from EAUSART to USART. Added silicon issue 11 (Data EEPROM).

### Rev D Document (05/2005)

Removed silicon issue 7 (Electrical Specifications), added silicon issue 11 (Reset), changed previous label of USART to EUSART in silicon issues 7, 8 and 9 (to be consistent with the data sheet) and added Data Sheet Clarification issue 1 (CCP).

### Rev E Document (08/2005)

Added Data Sheet Clarification issue 2 (Data EEPROM Memory).

### Rev F Document (03/2006)

Corrected part number revision IDs in the table on page one.

# PIC18F1220/1320

---

NOTES:

---

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


AmpLab, FilterLab, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, MPASM, MPLIB, MPLINK, MPSIM, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rFLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and Zena are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2006, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
== ISO/TS 16949:2002 ==**

*Microchip received ISO/TS-16949:2002 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona and Mountain View, California in October 2003. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



---

---

## WORLDWIDE SALES AND SERVICE

---

---

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Alpharetta, GA  
Tel: 770-640-0034  
Fax: 770-640-0307

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**  
Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**San Jose**  
Mountain View, CA  
Tel: 650-215-1444  
Fax: 650-961-0286

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8676-6200  
Fax: 86-28-8676-6599

**China - Fuzhou**  
Tel: 86-591-8750-3506  
Fax: 86-591-8750-3521

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Shunde**  
Tel: 86-757-2839-5507  
Fax: 86-757-2839-5571

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7250  
Fax: 86-29-8833-7256

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

**India - New Delhi**  
Tel: 91-11-5160-8631  
Fax: 91-11-5160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471-6166  
Fax: 81-45-471-6122

**Korea - Gumi**  
Tel: 82-54-473-4301  
Fax: 82-54-473-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Penang**  
Tel: 60-4-646-8870  
Fax: 60-4-646-5086

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-399  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820