

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [63813-5600](#)
Status: **Active**
Description: Extractor Tool for MP-Lock™ Quick Disconnect Receptacle Terminals

Documents:

[RoHS Certificate of Compliance \(PDF\)](#)


General

| | |
|--------------------------------|--|
| Product Family | Application Tooling |
| Series | T0201 |
| Comments | See Tooling Specification (PDF) Above |
| Function | Extraction |
| Geographic Area | Global |
| Level of Automation | Manual |
| More Detailed Tech Information | applicationtooling@molex.com |
| Product Name | N/A |
| Survey | www.molex.com//review/apptool_survey.html |
| Tool Type | Handtool |
| UPC | 883906944421 |

Material Info

Reference - Drawing Numbers

| | |
|-------------------------------|---------------|
| Application Tooling Documents | ATS-638135600 |
|-------------------------------|---------------|



EU RoHS **China RoHS**

Compliance Status

Not Reviewed

REACH SVHC

Not Reviewed

Low-Halogen Status

Not Reviewed

Need more information on product environmental compliance?

Email productcompliance@molex.com
 For a multiple part number RoHS Certificate of Compliance, [click here](#)

Please visit the [Contact Us](#) section for any non-product compliance questions.

Search Parts in this Series

[T0201Series](#)

Use With

[MP-Lock™ Quick Disconnect 35097](#)

Application Tooling | **FAQ**
Description **Product #**

| | |
|---|------------|
| MP-Lock™ Quick Disconnect with Vibration Support, Female, for 20-26 AWG (0.50-0.12mm ²), Metal Strip, Tab 2.79 x 0.51mm, Pre-Tin Plated | 0350979702 |
| MP-Lock™ Quick Disconnect with Vibration Support, Female, for 16-20 AWG (1.30-0.50mm ²), Metal Strip, Tab 2.79 | 0350979802 |

x 0.51mm, Pre-Tin
Plated

This document was generated on 03/08/2013

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION